

EAST AYRSHIRE COUNCIL
DEPARTMENT OF EDUCATIONAL AND SOCIAL SERVICES
EDUCATION CAPITAL PROGRAMME 2001/2002

PROJECT		2000/2001 £000's	FUNDED £000's
COMMUNITY EDUCATION			50
CRAIGMALLOCH OUTDOOR CENTRE	UPGRADE SHOWER FACILITIES	3	
DOON VALLEY SWIMMING POOL	JOINT VENTURE WITH COMMUNITY SERVICES	10	
DALRYMPLE COMMUNITY CENTRE	STORAGE HEATING UPGRADE	7	
GATEWAY CENTRE	KITCHEN UPGRADE	5	
HURLFORD COMMUNITY CENTRE	ROOF REPAIRS AND FABRIC UPGRADE	12	
NEWMILNS SKI SLOPE	REPAIR TO TOW ROPE	3	
OCHILTREE COMMUNITY CENTRE	STORAGE HEATING UPGRADE	7	
SHORTLEES COMMUNITY CENTRE	STAIR TOP PROTECTION	3	
		50	
DISABLED PROVISION/SEN ADAPTATIONS			113
AUCHINLECK ACADEMY	INTERNAL HANDRAILS AND IMPROVED ACCESS	5	
FLOWERBANK NURSERY	INTERNAL ACCESS	8	
GARGIESTON PRIMARY	TOILET AND CHANGING AREA	25	
KILMAURS NURSERY	EXTERNAL ACCESS	8	
LAINSHAW PRIMARY	IMPROVED DISABLED ACCESS	10	
OCHILTREE CEC	PARKING BAYS FOR PEOPLE WITH A DISABILITY	2	
SHORTLEES PRIMARY	TOILET AND CHANGING AREA/IMPROVED INTERNAL ACCESS	20	
ST COLUMBA'S PRIMARY	TOILET AND CHANGING AREA	20	
ST MATTHEW'S PRIMARY	IMPROVED DISABLED ACCESS	5	
V I UNIT - GRANGE ACADEMY	ENHANCEMENT FOR V I MOBILITY	10	
		113	
EARLY YEARS			55
CAIRNS NURSERY	MAINS DRINKING WATER - PIPE REPLACEMENT	5	
DARVEL NURSERY SCHOOL	FIRE EXIT DOOR UPGRADE	4	
DRONGAN NURSERY SCHOOL	ENCLOSED RAMPED ENTRANCE AND INTERNAL SECURITY MEASURES	10	
KILMAURS NURSERY SCHOOL	TOILET UPGRADE / DRAINAGE ISSUES	10	
NEW CUMNOCK NURSERY SCHOOL	ENTRANCE UPGRADE	5	
ONTHANK NURSERY	LIGHTING UPGRADE	6	
RICCARTON NURSERY SCHOOL	TOILET UPGRADE	15	
		55	
HEALTH AND SAFETY			100
DARVEL PRIMARY	WINDOW REFURBISHMENT - PHASE 1	20	
GREENMILL PRIMARY	WINDOW REFURBISHMENT - PHASE 2	10	
VARIOUS ESTABLISHMENTS	CONTINGENCY FOR EMERGENCIES	50	
VARIOUS ESTABLISHMENTS	PLAYGROUND SURFACE UPGRADES	20	
		100	
MAJOR CAPITAL WORKS			735
DARVEL PRIMARY	ROOF REPAIRS	40	
LOANHEAD PRIMARY	REINSTATEMENT OF DINING HALL	100	
NEWMILNS PRIMARY	BOILER PLANT REPLACEMENT	75	
NEWMILNS PRIMARY	ACCOMMODATION ISSUES	290	
PATNA PRIMARY	ASBESTOS REMOVAL	80	
ST MATTHEW'S PRIMARY	BOILER PLANT REPLACEMENT	75	
ST SOPHIA'S PRIMARY	BOILER PLANT REPLACEMENT	75	
		735	
MINOR CAPITAL WORKS			105
DARVEL PRIMARY	ROOF REPAIRS	40	

**EAST AYRSHIRE COUNCIL
DEPARTMENT OF EDUCATIONAL AND SOCIAL SERVICES
EDUCATION CAPITAL PROGRAMME 2001/2002**

HILLHEAD PRIMARY	WINDOW UPGRADE - PHASE 1	30	
KILMAURS PRIMARY	ROOF REPAIRS	35	
		105	
PROJECTS			262
FUTURE DEVELOPMENTS	SITE INVESTIGATIONS	5	
GALSTON PRIMARY	NEW BUILD - PRELIMINARY WORKS	257	
		262	
RETENTIONS			80
PREVIOUS PROJECTS	RETENTIONS	80	
		80	
SCHOOL SECURITY			140
BELLSBANK PRIMARY	SECURITY MEASURES/ACCESS	10	
DRONGAN PRIMARY	CCTV SYSTEM AND SECURITY LIGHTING	60	
JAMES HAMILTON ACADEMY	SECURITY MEASURES AT RECEPTION AREA AND EXTERNAL DOORS	40	
KILMARNOCK ACADEMY	EXTERNAL DOOR SECURITY	30	
		140	
SPEND TO SAVE			40
VARIOUS	PROPERTY RATIONALISATION	30	
VARIOUS ESTABLISHMENTS	DRAUGHT PROOFING WINDOWS	10	
		40	
TRAFFIC MANAGEMENT			20
VARIOUS ESTABLISHMENTS	VEHICULAR SEGREGATION/SAFETY MEASURES	20	
		20	
TOTAL			1700